

Proposed Code Change State Form 41186R

RETURN TO: INDIANA DEPARTMENT OF HOMELAND SECURITY CODE SERVICES SECTION 302 W. Washington Street Room W246 Indianapolis, IN 46204

FOR OFFICE USE ONLY					
Recei	ived 7/17/09				
Code	50.10.2-09				

INSTRUCTIONS:

Only TYPED copy accepted.

(KEY - Dashed line through material to be deleted, underline material to be added)

Use second sheet for any material requiring more space.

Code Title	Edition						
2009 Indiana Residential Code	First Edition						
Section number and title	Page						
R602.7.3 location		1 of 1					
Proponent	Title						
Craig Wagner	Chief Building Inspecto	or/ IABO Code Comm. Member					
Address		Phone					
220 W Van Buren St, Columbia City IN 46725	260-248-3111						
PROPOSED CODE CHANGE (Check One)							
□ Change to read as follows □ Delete and substitute as follows □ Delete without substitution Section R602.7.3, Location. Headers less than 2 inches (51 mm) in width or built up of							
members less than 2 inches (51 mm) in width that		, ,					
less than 4 inches (102 mm) in width or built up o	f members less than 4	inches (102 mm) in					
width that span more than 16 feet (4,877 mm) sha	ll be located at the top	of the wall immediately					
below the top plate.							
Exception: When a minimum of 3/8 inch (10 mm) structural wood shea	thing is applied from the					
bottom of the header to the top of the wall and all	joints on structural me	embers are fastened in					
accordance with TABLE R602.3(1) or TABLE R6	•						
	().						
REASON AND FI	SCAL IMPACT						
This amendment, brought forward from the 20	005 InRC, is in respo	onse to problems					
encountered in the field with rotation of long headers when not restrained at the top.							
onodiniored in the hold with retation of long headers when het restrained at the top.							
Fiscal impact: no increase to the cost of construction.							
REVIEW RECOMMENDATION							
Approve							
Disapprove							
Approve as amended							
Further Study							